



<b>OPEL Agila: 1FTP984</b>			
Vinnnumber:	<b>WOLFXB32SDM758553</b>	Versionname:	<b>AGILA Enjoy 94PK</b>
First Registrationdate:	<b>22/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>62063</b>	Power Kw:	<b>69</b>
Bodytype:		Body color:	<b>Green</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2731</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>185/60/15/88 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>	
Emergency spare wheel	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>587,56</b>
<b>Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>246,56</b>



<b>Alloy rim R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>95,00</b>
---	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Antenna base, Damaged, E - Replace 44,00



Aerial, Broken, E - Replace 12,00



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*