



PEUGEOT 2008: 1GFD938

Vinnumber:	VF3CU8HR0EY001294	Versionname:	2008 Active 68PK
First Registrationdate:	22/01/2014	Fiscalpower:	
Expertise Mileage:	120056	Power Kw:	50
Bodytype:		Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3821
Maintenance:	IN 18400 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/16/89 H Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	412,67
-------------------	---------------

Ceiling, Hole, Smart repair	64,32
-----------------------------	--------------




Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display


Interior, Dirty, Chemical cleaning	0,00
------------------------------------	-------------



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Dirty, Acceptable 0,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Door F L, Bump(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Damaged, E - Replace 30,00

