



RENAULT Clio: 1HFL599

Vinnnumber:	VF15R7A0H51288379	Versionname:	CLIO IV BER e-Business St&St 90PK
First Registrationdate:	8/07/2014	Fiscalpower:	
Expertise Mileage:	16831	Power Kw:	66
Bodytype:	Hatchback	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2230
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Rear parking sensors	
Radio multimedia	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Jack	Yes
------	------------

Total cost ex VAT	790,58
-------------------	---------------

Wheel cover R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wheel cover R R, Missing, E - Replace	24,00
---------------------------------------	--------------



Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
---	---------------





Interior, Dirty, Cleaning 0,00



Wheel cover F R, Damaged, E - Replace 24,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Tailgate, Scratch(es), LI - Repair and paint (complete) 241,34

