


**RENAULT Grand Scenic: 1FXC876**

Vinnnumber:	<b>VF1JZ14M649826191</b>	Versionname:	<b>GRAND SCENIC Energy Intens 5pl.110PK</b>
First Registrationdate:	<b>25/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>94006</b>	Power Kw:	<b>81</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>4814</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/17/95 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

 Total cost ex VAT 298,20

 Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00

 Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

 Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

 Alloy rim F R, Damaged, E - Replace 235,20



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting 63,00



Roof pillar L, Bump(s), PDR - Knock out without painting 0,00



Bodywork, Difference in color, Acceptable 0,00

