



RENAULT Clio: 1FUH843

Vinnumber:	VF15R040H49899663	Versionname:	CLIO IV BER Expression
First Registrationdate:	28/10/2013	Fiscalpower:	75PK
Expertise Mileage:	71077	Power Kw:	55
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1204
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Jack	Yes
------	------------

Total cost ex VAT	645,20
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Damaged, E - Replace	240,00



Wheel cover F R, Damaged, E - Replace	24,00
---------------------------------------	--------------



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Wheel cover R R, Damaged, E - Replace 24,00



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display