


PEUGEOT 5008: 1FIQ649

| | | | |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | VF30A9HD8DS130455 | Versionname: | 5008 Access FAP 115PK |
| First Registrationdate: | 9/07/2013 | Fiscalpower: | |
| Expertise Mileage: | 152160 | Power Kw: | 84 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3633 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|-------------------------|-------------------------------|-----------------|-------------------|
| Radio CD | | Luggage cover | |
| GPS storage | | Type of Tow bar | No Tow bar |
| GPS storage | HD | | |
| Windows electric F | | | |
| Cruise Control | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| 215/55/16/97 V Steel | | | | |
|----------------------|-------|-----------------------|-------|-----------------------|
| Summer tyres: | Fr.L. | Kleber: 5 mm | Fr.R. | Kleber: 5 mm |
| | Re.L. | Michelin: 3 mm | Re.R. | Michelin: 3 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 534,40 |
|-------------------|--------|

| | |
|--|------|
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Wing R R, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|--------|



| | |
|--|--------|
| Bumper corner R L, Scratch(es), It - Spot repair | 115,56 |
|--|--------|



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64

