



SKODA Octavia: 1EBN413

Vinnnumber:	TMBHT21Z4D2068945	Versionname:	OCTAVIA COMBI GTec Ambition DPF 105PK
First Registrationdate:	11/10/2012	Fiscalpower:	
Expertise Mileage:	171838	Power Kw:	77
Bodytype:	Break	Body color	Beige
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2209
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1679,48

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Tyre F R, Damaged, E - Replace 132,00



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00





Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20

