



VOLKSWAGEN MULTIVAN: 1NUA073

Vinnumber:	WV2ZZZ7HZGH112432	Versionname:	
First Registrationdate:	26/04/2016	Fiscalpower:	
Expertise Mileage:	149999	Power Kw:	110
Bodytype:	Bus	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2505
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/16/102 H LightMetal			
Summer tyres:	Fr.L.	Other: 7 mm	Fr.R.	Other: 7 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1468,07
-------------------	----------------

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	---------------



Rearview mirror housing R, Scratch(es), Smart repair	110,64
--	---------------



Reflector, Damaged, E - Replace 20,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete) 238,76




Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 158,85



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

231,15

