



VOLKSWAGEN PASSAT: 1LKH280

Vinnnumber:	WVWZZZ3CZGE079098	Versionname:	2.0 TDI MSQ COMFORTLINE
First Registrationdate:	12/10/2015	Fiscalpower:	
Expertise Mileage:	168260	Power Kw:	110
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1702
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	Tow bar fixed
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting LED	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1419,59

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80





Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Interior, Dirty, Cleaning 50,00



Door panel R R, Damaged, E - Replace 114,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Damaged, E - Replace	0,00

