



VOLKSWAGEN Golf: 1GSS458			
Vinnnumber:	WVWZZZAUZEW312628	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	17/04/2014	Fiscalpower:	
Expertise Mileage:	130353	Power Kw:	77
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2422
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment	
Emergency spare wheel	Yes

Total cost ex VAT	583,64
Front bumper, Scratch(es), Acceptable	0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Reflector, Damaged, E - Replace 20,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Wing F L, Bump(s), PDR - Knock out without painting 63,00

