



| VOLVO V60: 1FHM347 | | | |
|-------------------------|--------------------------|--------------|---------------------------------|
| Vinnumber: | YV1FW8481E1156810 | Versionname: | V60 BRE D2 Kinetic 115PK |
| First Registrationdate: | 1/07/2013 | Fiscalpower: | |
| Expertise Mileage: | 145897 | Power Kw: | 84 |
| Bodytype: | Break | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2511 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| Options | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Summer tyres: | 205/60/16/96 W LightMetal | | | |
| | Fr.L. | Kleber: 7 mm | Fr.R. | Kleber: 7 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

| Assistance equipment | | | |
|--|------------|------------|--------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 95,00 |
| Wing R L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Alloy rim R L, Damaged, LI - Repair and paint (complete) | | | 95,00 |



| | | | |
|-----------------------------------|--|--|-------------|
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
|-----------------------------------|--|--|-------------|

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |