



AUDI A5: 1FH0773			
Vinnumber:	WAUZZZ8T9EA002795	Versionname:	A5 SB DPF Multitr. 136PK Aut.
First Registrationdate:	1/07/2013	Fiscalpower:	
Expertise Mileage:	169634	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1408
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Emergency spare wheel	Yes

Total cost ex VAT	613,37
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), Le - Replace and paint	0,00



Front bumper - Scratch(es), L - Repair and paint (complete)	254,16
---	---------------

Front bumper, scratch(es), LI - Repair and paint (complete) 264,10



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bad repair, Acceptable 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 264,21



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bad repair, Acceptable 0,00

