



## CITROEN C4 Picasso: 1FBE103

Vinnumber:	<b>VF7UA9HR8DJ614901</b>	Versionname:	<b>GR.C4 PICASSO Bus.GPS</b>
First Registrationdate:	<b>14/05/2013</b>	Fiscalpower:	<b>FAP 112PK</b>
Expertise Mileage:	<b>115288</b>	Power Kw:	<b>82</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 4500 KM</b>	Parking lot:	<b>2129</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Radio CD	Luggage cover
GPS storage	<b>HD</b> Rear parking sensors
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/55/16/95 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT 1287,30

Sill outer R, Dent(s), LI - Repair and paint (complete) 310,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Broken, Le - Replace and paint 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), LI - Repair and paint (complete) 308,20




Dashboard, Scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Stain, Cleaning 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Seat cover F L, Stain, Cleaning 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R L, Stain, Cleaning 0,00

No pictures to display

Ignition key, Broken, E - Replace 150,00



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display