



BMW X5: TF6001			
Vinnumber:	WBAK5410X00R86451	Versionname:	3.0 XDRIVE30D 4WD AUTO
First Registrationdate:	8/08/2016	Fiscalpower:	
Expertise Mileage:	95250	Power Kw:	190
Bodytype:	SUV	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4527
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			








Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	275/40/20/106 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
Total cost ex VAT	1629,57
Roof, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60



Bonnet, Scratch(es), LI - Repair and paint (complete)	348,09
---	---------------

	Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
	Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
	Wing R L, Scratch(es), It - Spot repair	115,56
	Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
	Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	Door panel R L, Hole, Acceptable	0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		
<i>No pictures to display</i>		
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)		
	Alloy rim R R polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		