







FIAT FREEMONT: CC6899

Vinnumber:

First Registrationdate: 16/02/2014 Expertise Mileage: 121360 Bodytype: Gearbox: MAN 6 VIT Transmission: Front Fueltype: Diesel Maintenance ок Battery functioning Yes Number of doors 5 Number of seats 7 Number head rests 7 Rims summer Aluminium Category Passenger Car

3C4PFACY5FT558331

2.0 MULTIJET 100KW Versionname: **BLACK CODE** Fiscalpower: Power Kw: 100 Body color Dark Grey Paint type Metalic Rims summer Aluminium Oil level ок Parking lot 3822

Oil level Options

 Radio CD
 Steats R heated

 GPS storage
 Seats electric F L

 GPS storage
 HD
 Central consol F

 Windows electric F
 Luggage cover

 Windows electric R
 Rear parking sensors

 Cruise Control
 Type of Tow bar

OK

Steering wheel multifunctional

Seats F heated

Type of headlighting Headlighting Halogen
Type of GPS GPS big screen color
Type of Lining Lining leather
Type of climate control Autom climate control

nsors
No Tow bar

Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Power steering	Yes
Idle position	ок	Sound engine	ок
Engine startingtime	ок	Clutch test	ок
Exhaust gass	ок	Wiper fluid level	ок
Handbrake	ок	Transmission	ок
		Lighting	ок
		Wiperblades	OK

Degree of wear

Summer tyres:

225/55/19	/103 V LightMetal		
Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes Jack	Yes
Total cost ex VAT		190,00
Seat cover F L, Deformed / Strained, Acceptable		0,00





Alloy rim F R	Scratch(es).	LI - Repair a	nd paint	(complete)
rundy runn i it	ooratonloop	Li itopuii u	ma pame	(oompioto)



95,00

