


**FORD Galaxy: 1FGK447**

Vinnnumber:	<b>WF0MXXGBWMDR44065</b>	Versionname:	<b>GALAXY Trend DPF 136PK</b>
First Registrationdate:	<b>21/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>108323</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4624</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

215/60/16/99 H LightMetal				
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>288,00</b>
Front bumper, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F R, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bonnet, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Roof pillar L, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Dent(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Luggage space cover, Missing, E - Replace			<b>288,00</b>



Wing R R, Dent(s), Acceptable

0,00

*No pictures to display*