



PEUGEOT 308: 1HDU584

Vinnnumber:	VF3LCBHXHES153576	Versionname:	308 SW BlueHDi Active STT 116PK
First Registrationdate:	26/06/2014	Fiscalpower:	
Expertise Mileage:	179074	Power Kw:	85
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3408
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	95,00
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Engine, Damaged, Diagnosis	0,00
<i>No pictures to display</i>	
Floor covering F L, Damaged, Acceptable	0,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim F R polished, Rust, Acceptable	0,00
--	------

No pictures to display

Engine, Not functioning (well), Diagnosis	0,00
---	------



Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display