



PEUGEOT 308: GA4267

Vinnnumber:	VF3LB9HCGES269426	Versionname:	1.6 E-HDI 84KW S/S ACTIVE
First Registrationdate:	8/12/2014	Fiscalpower:	
Expertise Mileage:	55987	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3816
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2760,14
Rear window, Damaged, E - Replace	370,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35





Wing R L, Dent(s), PDR - Knock out without painting 82,80



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 502,50




Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Knock out without painting 122,40



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Ceiling, Stain, Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

