



OPEL Astra: 1FJG091

Vinnumber:	W0LPC6DA7D1128875	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	33319	Power Kw:	70
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1120
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	857,51
Door R R, Scratch(es), LI - Repair and paint (complete)	318,35




Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
--	---------------





Rear window, Scratch(es), E - Replace

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Outer door handle R R, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Scratch(es), E - Replace

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

