


OPEL Vivaro 2700: 1HER915

Vinnnumber:	WOLF7A1A9EV631889	Versionname:	VIVARO 2700 B/F L1H1 Ec.DPF(E5)115PK Aut
First Registrationdate:	2/07/2014	Fiscalpower:	
Expertise Mileage:	209702	Power Kw:	85
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV03
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/105 T Steel			
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	440,00
-------------------	--------

Bodywork, Not original part, Acceptable	0,00
---	------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Wheel cover R R, Missing, E - Replace 22,50



Wheel cover F L, Missing, E - Replace 22,50



Wheel cover R L, Missing, E - Replace 22,50



Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 200,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Missing, E - Replace 22,50

