


OPEL Astra: 1HBR419

Vinnnumber:	WOLPD8EA2E8060145	Versionname:	ASTRA BRE ecoFLEX Enjoy St&St 95PK
First Registrationdate:	12/06/2014	Fiscalpower:	
Expertise Mileage:	57568	Power Kw:	70
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4830
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1310,11
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Bad repair, Acceptable	0,00



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Chemical polution, LI - Repair and paint (complete)	220,18



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

