



<b>BMW 3: 1HJV529</b>			
Vinnumber:	<b>WBA3Y11030D450113</b>	Versionname:	<b>3 GRAN TURISMO 318d</b>
First Registrationdate:	<b>5/08/2014</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>103769</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2513</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>





<b>Degree of wear</b>			
Summer tyres:	<b>225/55/17/97 Y LightMetal</b>		
	Fr.L.	Fr.R.	
	<b>Michelin: 3 mm</b>	<b>Michelin: 3 mm</b>	
	Re.L.	Re.R.	
	<b>Uniroyal: 4 mm</b>	<b>Uniroyal: 4 mm</b>	

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

<b>Total cost ex VAT</b>	<b>390,36</b>
<b>Front bumper, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Wing R R, Dent(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Bonnet, Stone chip(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Wing R L, Dent(s), PDR - Knock out without painting</b>	<b>63,00</b>



<b>Door R L, Dent(s), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	

Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), It - Spot repair	115,56
	
Windscreen, Stone chip(s), Windscreen repair	0,00
	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Tear, Acceptable	0,00
	
Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	