



BMW 2 gt: 1RVL983

Vinnumber:	WBA2E310205F42195	Versionname:	
First Registrationdate:	13/03/2017	Fiscalpower:	
Expertise Mileage:	14705	Power Kw:	85
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2426
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Kumho: 3 mm	Fr.R.	Kumho: 3 mm
	Re.L.	Kumho: 5 mm	Re.R.	Kumho: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			669,48
Tailgate, Dent(s), LI - Repair and paint (complete)			301,68



Reflector, Broken, E - Replace 30,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 337,80

