


BMW 3: 1GBG432

Vinnumber:	WBA3X110X0D700711	Versionname:	3 GRAN TURISMO 320iA
First Registrationdate:	13/12/2013	Fiscalpower:	163PK Aut.
Expertise Mileage:	35321	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	2/12/2017	Parking lot:	1124
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/18/95 W LightMetal				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Runflat **Yes**

Total cost ex VAT	1282,62
Door F L, Dent(s), PDR - Knock out without painting	63,00



Alloy rim F L, Scratch(es), Acceptable **0,00**

No pictures to display

Bumper R, Dent(s), Acceptable **0,00**

No pictures to display

Maintenance, Maintenance, Execute **0,00**



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



