


NISSAN Qashqai: 1ESB872

Vinnnumber:	SJNFEAJ10U2714982	Versionname:	QASHQAI 2WD Urban Edition St/St 130PK
First Registrationdate:	6/03/2013	Fiscalpower:	
Expertise Mileage:	91430	Power Kw:	96
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3807
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Panoramic roof	
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/18/95 H LightMetal			
Winter tyres:	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Firestone: 7 mm	Re.R.	Firestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1246,04
-------------------	---------

Rocker panel inner R R, Scratch(es), Acceptable	0,00
-------------------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Smart repair	110,64
-------------------------------------	--------





Bumper F L, Scratch(es), Smart repair 110,64



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Sill outer R, Scratch(es), It - Spot repair 115,56



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Broken, E - Replace 49,40



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Dent(s), PDR - Knock out without painting	63,00
-----------------------------------------------------	-------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
-------------------------------------------------------------	--------



Certificate Of Conformity, Missing, E - Replace	150,00
-------------------------------------------------	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display