



## PEUGEOT Partner: 1GWA275

|                                    |                                 |              |   |
|------------------------------------|---------------------------------|--------------|---|
| Vinnnumber:                        | <b>VF37A9HF0EN517335</b>        | Versionname: | <b>PARTNER B/F L1H1<br/>Conf.120 90PK</b> |
| First Registrationdate:            | <b>15/05/2014</b>               | Fiscalpower: |   |
| Expertise Mileage:                 | <b>199648</b>                   | Power Kw:    | <b>66</b>                                 |
| Bodytype:                          | <b>Transporter</b>              | Body color:  | <b>White</b>                              |
| Gearbox:                           | <b>MAN 5 VIT</b>                | Paint type:  | <b>Metalic</b>                            |
| Transmission:                      |                                 | Rims summer: | <b>Steel</b>                              |
| Fueltype:                          | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                                 |
| Battery functioning:               | <b>Yes</b>                      | Parking lot: | <b>2110</b>                               |
| Number of doors:                   | <b>5</b>                        |              |   |
| Number of seats:                   | <b>2</b>                        |              |   |
| Number head rests:                 | <b>2</b>                        |              |   |
| Rims summer:                       | <b>Steel</b>                    |              |   |
| Category:                          | <b>Light Commercial Vehicle</b> |              |   |
| Oil level:                         | <b>OK</b>                       |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>                      |              |   |

## Options

|                         |                               |                      |
|-------------------------|-------------------------------|----------------------|
| Radio CD                | Type of Tow bar               | <b>Tow bar fixed</b> |
| Windows electric F      |                               |                      |
| Cruise Control          |                               |                      |
| Type of headlighting    | <b>Headlighting Halogen</b>   |                      |
| Type of GPS             | <b>No GPS</b>                 |                      |
| Type of Lining          | <b>Lining fabrics</b>         |                      |
| Type of climate control | <b>Manual climate control</b> |                      |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>195/65/15/91 T Steel</b> |                          |       |                          |
| Winter tyres: | Fr.L.                       | <b>Continental: 3 mm</b> | Fr.R. | <b>Continental: 3 mm</b> |
|               | Re.L.                       | <b>Continental: 2 mm</b> | Re.R. | <b>Continental: 1 mm</b> |

## Assistance equipment

|             |            |
|-------------|------------|
| Spare wheel | <b>Yes</b> |
|-------------|------------|

|   |        |
|---|--------|
| Total cost ex VAT   | 232,88 |
| Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 232,88 |

