



MERCEDES C: 1GNX778

Vinnnumber:	WDD2042001G217931	Versionname:	C BRE 180 CDI BlueEFF. S&S 120PK
First Registrationdate:	21/03/2014	Fiscalpower:	
Expertise Mileage:	56230	Power Kw:	88
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2328
Maintenance:	SERVICE A IN 280D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
GPS storage	Front parking sensors
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining artificial leather and alcantara
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Yokohama: 6 mm	Fr.R.	Yokohama: 6 mm
	Re.L.	Yokohama: 5 mm	Re.R.	Yokohama: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 2079,60

Alloy rim R L polished, Scratch(es), I - Repair 155,00






Alloy rim F R polished, Scratch(es), E - Replace 235,20



Alloy rim R R polished, Scratch(es), E - Replace 235,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L polished, Damaged, E - Replace 235,20



Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Stone chip(s), E - Replace 487,20



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display