



BMW X5: TE5872

Vinnumber:	WBAKS210800H98230	Versionname:	X5 2.0dA xDrive25 218PK Aut.
First Registrationdate:	6/08/2014	Fiscalpower:	
Expertise Mileage:	74342	Power Kw:	160
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3812
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/55/18/109 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	572,34
-------------------	---------------

Ceiling, Damaged, Smart repair	64,32
--------------------------------	--------------



Door R L, Dent(s), PDR - Knock out without painting	63,00
---	--------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Door F R, Dent(s), PDR - Knock out without painting	63,00
---	-------

