



RENAULT CLIO: 1LNU739			
Vinnnumber:	VF15R0J0A54118343	Versionname:	1.5 ENERGY DCI 90E EXPRESSION
First Registrationdate:	30/10/2015	Fiscalpower:	
Expertise Mileage:	54796	Power Kw:	66
Bodytype:	Hatchback	Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2806
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Windows electric F		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/92 T Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm




Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	694,68
Wing R L, Scratch(es), LI - Repair and paint (complete)	246,56



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	0,00



<p>Door R L, Scratch(es), LI - Repair and paint (complete)</p> 	<p>254,68</p>
<p>Wheel cover F R, Scratch(es), E - Replace</p> 	<p>24,00</p>
<p>Wing F L, Scratch(es), Acceptable</p> <p><i>No pictures to display</i></p>	<p>0,00</p>
<p>Wheel cover R R, Scratch(es), Acceptable</p> <p><i>No pictures to display</i></p>	<p>0,00</p>
<p>Front bumper, Scratch(es), LI - Repair and paint (complete)</p> 	<p>169,44</p>