



VOLKSWAGEN Passat: 1FLN146

Vinnnumber:	WVWZZZ3CZEE026970	Versionname:	PASSAT BER Trendline BM
First Registrationdate:	7/08/2013	Fiscalpower:	105PK
Expertise Mileage:	141032	Power Kw:	77
Bodytype:	Berline	Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3511
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS base
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	392,35
-------------------	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wheel cover F.R. Broken, F. Replace	30,00
-------------------------------------	--------------

Wheel cover F R, Broken, L - Replace 0,00




Bonnet, Hail damage, Le - Replace and paint 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 0,00



Roof, Hail damage, PDR - Hail 0,00




Rearright R tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Hail damage, PDR - Hail 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Hail damage, PDR - Hail

0,00



Moulding windscreen L, Missing, E - Replace

44,00

