



**RENAULT Megane: 1FMY112**

Vinnnumber:	<b>VF1KZNA0649527343</b>	Versionname:	<b>MEGANE GT Energy Bose Ed.130PK</b>
First Registrationdate:	<b>23/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>119816</b>	Power Kw:	<b>96</b>
Bodytype:	<b>Break</b>	Body color	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2215</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/50/17/98 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>579,00</b>
-------------------	---------------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
-----------------------------------------------------------------------	--------------



Headlight protector F R, Broken, E - Replace	<b>20,00</b>
----------------------------------------------	--------------



Door trim F R, Deformed / Strained, E - Replace 114,00



Roof, Hail damage, PDR - Hail 350,00



Wing R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Maintenance book, Missing, E - Replace 0,00

*No pictures to display*