



TOYOTA AURIS TOURING SPORTS: 1NTG725

Vinnumber:	SB1ZS3JE40E246246	Versionname:	1.8 HYBRID LOUNGE CVT
First Registrationdate:	21/04/2016	Fiscalpower:	AUTO
Expertise Mileage:	44093	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3504
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 785,52

Interior, Dirty, Chemical cleaning 152,58





Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Scratch(es), LI - Repair and paint (complete) 310,50



Roof, Dent(s), Acceptable 0,00



Roof pillar L, Dent(s), Acceptable 0,00



Internal Boot Lining L, Scratch(es), Smart repair 110,64



Wing R R, Dent(s), Acceptable 0,00



Roof pillar R, Dent(s), Acceptable 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

Any tint L, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00



Backrest cover R L, Deformed / Strained, P - Check 0,00

