


RENAULT Grand Scenic: 1GED696

Vinnnumber:	VF1JZNAB650099451	Versionname:	GRAND SCENIC Energy Intens 7pl.130PK
First Registrationdate:	14/01/2014	Fiscalpower:	
Expertise Mileage:	91454	Power Kw:	96
Bodytype:		Body color	Burgundy
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3532
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm






















Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1259,31
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Dashboard, Scratch(es), Smart repair	110,64
--------------------------------------	--------

			Bumper R, Scratch(es), Acceptable	0,00
			Luggage space cover, Hole, Smart repair	110,64
			Wing F L, Scratch(es), Acceptable	0,00
			Door R L, Dent(s), It - Spot repair	115,56
			Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
			Wing R L, Dent(s), Acceptable	0,00
			Door F R, Dent(s), It - Spot repair	115,56
			Door R R, Dent(s), LI - Repair and paint (complete)	318,35
			Rocker panel inner R L, Dent(s), Acceptable	0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Rocker panel inner R R, Scratch(es), Acceptable

0,00



Door R R, Dent(s), It - Spot repair

115,56



Door F R, Dent(s), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Dent(s), Acceptable

0,00



Ceiling, Stain, Cleaning

25,00



Roof, Dent(s), PDR - Knock out without painting

63,00

