



TOYOTA AURIS TOURING SPORTS: 1PHN914

Vinnumber:	SB1ZS3JE10E265207	Versionname:	1.8 HYBRID LOUNGE CVT AUTO
First Registrationdate:	7/07/2016	Fiscalpower:	
Expertise Mileage:	50757	Power Kw:	100
Bodytype:		Body color:	Red
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	2322
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	694,76
Mirror side blinker R, Broken, E - Replace	30,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper grille F R, Scratch(es), E - Replace 32,40



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, P - Check 0,00



Tailgate, Scratch(es), It - Spot repair 115,56



Rocker panel inner R L, Scratch(es), Forfeit 115,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Certificate Of Conformity, Missing, P - Check 0,00

No pictures to display

Tires, Out of tolerance, P - Check 0,00



Bumper grille, Scratch(es), Acceptable 0,00

No pictures to display