



VOLVO XC70: 1FK0067

Vinnnumber:	YV1BZ83A4E1179911	Versionname:	XC70 D5 4WD Kinetic
First Registrationdate:	29/07/2013	Fiscalpower:	215PK
Expertise Mileage:	153257	Power Kw:	158
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3819
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/50/18/97 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	264,00
-------------------	--------

Floor covering F L, Hole, E - Replace	264,00
---------------------------------------	--------



Bumper cover R M, Scratch(es), Acceptable	0,00
---	------



Wing R L, Chemical polution, 67 - Polish 0,00



Tailgate, Scratch(es), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Door F R, Repaired, P - Check 0,00



Door F L, Dent(s), Acceptable 0,00



Alloy rim F L, Scratch(es), Acceptable 0,00

