



| VOLVO XC60: 1HCS807 | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | YV1DZ73C1F2636801 | Versionname: | XC60 D4 Kinetic 181PK |
| First Registrationdate: | 19/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 126735 | Power Kw: | 133 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4708 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Radio CD | | Seats electric F L | |
| GPS storage | HD | Seats electric F R | |
| GPS storage | | Panoramic roof | |
| Windows electric F | | Central consol F | |
| Windows electric R | | Luggage cover | |
| Cruise Control | | Front parking sensors | |
| Steering wheel multifunctional | | Rear parking sensors | |
| Seats F heated | | Type of Tow bar | Tow bar removable |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|-----------------------------------|----------------------|-------|----------------------|
| Summer tyres: | 235/60/18/103 V LightMetal | | | |
| | Fr.L. | Pirelli: 5 mm | Fr.R. | Pirelli: 5 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

| Assistance equipment | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 396,72 |
| Wing R R, Dent(s), PDR - Knock out without painting | | | 102,60 |



| | | | |
|---|--|--|--------------|
| Door R L, Dent(s), PDR - Knock out without painting | | | 63,00 |
|---|--|--|--------------|



Bumper corner R L, Scratch(es), It - Spot repair 115,56



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56

