



VOLKSWAGEN Golf: 1EXN394

Vinnnumber:	WVWZZZAUZDP071922	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	15/04/2013	Fiscalpower:	
Expertise Mileage:	156731	Power Kw:	77
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2701
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	0,00
Roof, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
No pictures to display	
Interior, Dirty, Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bodywork, Not original part, Sticker removal	0,00
No pictures to display	
Wing R R, Dent(s), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00

No pictures to display