



## VOLVO XC60: 1RAA032

Vinnnumber:	<b>YV1DZARCDH2075887</b>	Versionname:	<b>2.0 D3 2WD GEARTRONIC MOMENTUM</b>
First Registrationdate:	<b>24/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>33537</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2504</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>235/65/17/108 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Pirelli: 7 mm</b>	Re.R.	<b>Pirelli: 7 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	254,16
-------------------	--------

Alloy rim R L, Scratch(es), Acceptable	0,00
----------------------------------------	------

No pictures to display

Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
-------------------------------------------------------------------------	--------





Spoiler R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	