



TOYOTA YARIS: 1KXZ913

Vinnumber:	VNKKD3D300A185803	Versionname:	1.5 VVT-I HYBRID COMFORT AUTO
First Registrationdate:	29/07/2015	Fiscalpower:	
Expertise Mileage:	26838	Power Kw:	54
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4501
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD		
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/84 H Steel			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1402,73
-------------------	----------------

Bumper moulding F, Broken, E - Replace	11,52
--	--------------



Wheel cover F R, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>	
Wing F R, Deformed / Strained, Le - Replace and paint	448,01



Headlight R, Broken, E - Replace 336,00



Seat cover R R, Stain, Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Front bumper, Deformed / Strained, Le - Replace and paint 607,20



Wing R R, Repaired, No repair 0,00



Bumper R, Bad repair, Acceptable 0,00

