



BMW 3: 1HG225

Vinnnumber:	WBA3Y11080D450379	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	15/07/2014	Fiscalpower:	136PK
Expertise Mileage:	136617	Power Kw:	100
Bodytype:	Hatchback	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4610
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunction	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1783,91
-------------------	----------------

Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------




Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Dent(s), Le - Replace and paint 735,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20

