


RENAULT Clio: 1HCG184

Vinnnumber:	VF17R040H51174744	Versionname:	CLIO IV BRE Expression
First Registrationdate:	17/06/2014	Fiscalpower:	75PK
Expertise Mileage:	63432	Power Kw:	55
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1111
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1087,56
-------------------	----------------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	24,00
---	--------------



Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	24,00
---	--------------



Bonnet, Repaired, No repair 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Boot carpet, Missing, E - Replace 80,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), E - Replace 24,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Luggage space cover, Missing, E - Replace 192,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display