



AUDI A4: 1HFB569			
Vinnnumber:	WAUZZZ8K4FA013132	Versionname:	A4 AVANT Ultra 136PK
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	183594	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4616
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage	DVD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/60/16/92 W Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm


Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	1559,49
--------------------------	----------------

Rocker panel inner R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	268,18
--	---------------



Door R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
--	---------------



Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing R L, Dent(s), PDR - Knock out without painting 63,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Dent(s) and scratch(es), Le - Replace and paint 735,00



Backrest cover F L, Scratch(es), Smart repair 64,32

