



BMW 3: 1GHS464

Vinnumber:	WBA3D91010J413394	Versionname:	3 BER 316d 116PK
First Registrationdate:	11/02/2014	Fiscalpower:	
Expertise Mileage:	119965	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	BINNEN 30000 KM		
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1814,20
--------------------------	----------------

Wing R R, Dent(s), Acceptable	0,00
--------------------------------------	-------------



Tailgate, Dent(s), PDR - Knock out without painting	63,00
--	--------------



Door panel R R, Hole, Smart repair 110,64



Seat cover F L, Worn, P - Check 0,00



Door frame R L, Dent(s), It - Spot repair 115,56



Parking sensor R, Missing, Repair/replace (lump sum) 25,00



GPS, Broken, E - Replace 1500,00



Door frame R R, Dent(s), Acceptable 0,00



Door R R, Dent(s), Acceptable 0,00

