



**BMW 3: 1FGZ769**

Vinnumber:	<b>WBA3D11000J623440</b>	Versionname:	<b>3 BER 318d 143PK</b>
First Registrationdate:	<b>26/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>99302</b>	Power Kw:	<b>105</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 18000 KM</b>	Parking lot:	<b>3327</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
GPS storage	
GPS storage	<b>HD</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 4 mm</b>	Re.R.	<b>Pirelli: 4 mm</b>

**Assistance equipment**

	Runflat	<b>Yes</b>
--	---------	------------

Total cost ex VAT	390,36
-------------------	--------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------



Alloy rim F L, Scratch(es), Acceptable 0,00



Bumper F R, Dent(s) and scratch(es), It - Spot repair 115,56



Door R R, Dent(s), Acceptable 0,00



Door R L, Dent(s), PDR - Knock out without painting 63,00



Wing R R, Dent(s), Acceptable 0,00



Door F R, Dent(s), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

