



**RENAULT Trafic: 1EJR657**

Vinnnumber:	<b>VF1FLA0AEDV437477</b>	Versionname:	<b>TRAFIC 27 B/F L1H1 Gr.Conf.FAP(E5)90PK</b>
First Registrationdate:	<b>1/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>157809</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>UITVOEREN</b>		
Maintenance	<b>NOT OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>3</b>		
Number head rests	<b>3</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>No</b>		

**Options**

Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/16/107 T Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 7 mm</b>	Fr.R.	<b>Semperit: 7 mm</b>
	Re.L.	<b>Other: 5 mm</b>	Re.R.	<b>Other: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	<b>1300,40</b>
Wheel cover R R, Missing, E - Replace	<b>22,50</b>



Door R R, Dent(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

*No pictures to display*

Ignition key, Missing, E - Replace	<b>150,00</b>
------------------------------------	---------------

*No pictures to display*

Wheel cover F L, Missing, E - Replace	<b>22,50</b>
---------------------------------------	--------------



Door F L, Dent(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

Door L, Dent(s), Acceptable 0,00

No pictures to display

Engine, Not functioning (well), Repair/replace (lump sum) 0,00



Instrument panel cover, Missing, E - Replace 8,00



Wheel cover R L, Missing, E - Replace 22,50



Wheel cover F R, Missing, E - Replace 22,50



Front bumper, Scratch(es), E - Replace 398,40



Roof, Dent(s), PDR - Knock out without painting 354,00



Seat cover F L, Damaged, E - Replace 300,00

