



AUDI A1 SPORTBACK: 1PVD886

| | | | |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber: | WAUZZZ8XXHB025553 | Versionname: | 1.6 TDI 85kW |
| First Registrationdate: | 27/09/2016 | Fiscalpower: | |
| Expertise Mileage: | 70332 | Power Kw: | 85 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4405 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|-------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Luggage cover |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Manual climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| 185/60/15/88 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

Total cost ex VAT 583,88

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



| | |
|-------------------------------|------|
| Tailgate, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|



| | |
|-------------------------------|------|
| Wing R R, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 169,44 |
|---|--------|

