


**BMW 3: 1HNP345**

Vinnumber:	<b>WBA3L11050K176858</b>	Versionname:	<b>3 TOURING 320d</b>
First Registrationdate:	<b>29/08/2014</b>	Fiscalpower:	<b>Eff.Dyn.Ed. 163PK</b>
Expertise Mileage:	<b>186781</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4126</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

205/60/16/92 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 2,5 mm	Re.R.	Michelin: 2,5 mm

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 2547,58

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Door panel F L, Damaged, E - Replace 114,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R, Scratch(es), LI - Repair and paint (complete) 310,50



Bumper R, Dent(s) and scratch(es), Le - Replace and paint 651,00



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Roof pillar L, Dent(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bad repair, Acceptable 0,00



Engine protective plate, Tear, E - Replace 95,20

