


**BMW 318 D: 1FJG069**

Vinnumber:	<b>WBA3K11000F825249</b>	Versionname:	<b>2.0 D</b>
First Registrationdate:	<b>15/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>178386</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2825</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/16/99 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 5 mm</b>	Fr.R.	<b>Bridgestone: 5 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>332,20</b>
-------------------	---------------

Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

*No pictures to display*

Bonnet, Stone chip(s), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>0,00</b>
---	-------------





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	332,20
---	--------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*