


BMW X3: 1LC5843

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | WBAWZ310300F65519 | Versionname: | 2.0 SDRIVE18D (110KW) |
| First Registrationdate: | 21/08/2015 | Fiscalpower: | |
| Expertise Mileage: | 93499 | Power Kw: | 110 |
| Bodytype: | SUV | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3512 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD | | Sun Roof electric | |
| GPS storage | | Panoramic roof | |
| GPS storage | HD | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | Type of Tow bar | No Tow bar |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 225/60/17/99 H LightMetal | | | |
| Winter tyres: | Fr.L. | Pirelli: 4 mm | Fr.R. | Pirelli: 4 mm |
| | Re.L. | Pirelli: 2 mm | Re.R. | Pirelli: 2 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

| | |
|---|------|
| Bumper R, Dent(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---|------|
| Ashtray, Deformed / Strained, E - Replace | 0,00 |
|---|------|



| | |
|-------------------------------|------|
| Wing R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

| | |
|--|------|
| <i>No pictures to display</i> | |
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |