


PEUGEOT 508: 1FKZ208

Vinnnumber:	VF38D9HL0DL005548	Versionname:	508 BER Active 115PK
First Registrationdate:	1/08/2013	Fiscalpower:	
Expertise Mileage:	146039	Power Kw:	84
Bodytype:	Berline	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	88,00
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Backrest cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Dirty, Cleaning	25,00



Door R L, Dent(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Steering wheel, Worn, Acceptable	0,00
----------------------------------	------



Wing R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Door panel R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Bad repair, Repair/replace (lump sum)	0,00
---	------

No pictures to display

Backrest cover R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display